



**POLARIS**

# TECHNICAL SERVICE BULLETIN

Date: December 10, 2015

## RZR

Bulletin Number: Z-15-04

Model Years: 2016

Safety Bulletin

Service Bulletin

Service Alert Fax

Distribution:  Owner/Principle  Service Manager  Sales Manager  Parts Manager  Technicians

*This Service Bulletin is located at [www.polarisdealers.com](http://www.polarisdealers.com)*

-Confidential and Proprietary-

### SUBJECT: 2016 RZR XP Turbo – Turbocharger Oil Drain Line Fastener Inspection

**PURPOSE:** Some 2016 RZR XP Turbo 2-seat models may have been manufactured with turbocharger oil drain line fasteners that do not meet the torque specification. The resulting issue could lead to oil leaking onto the engine and exhaust head pipe.

#### AFFECTED MODELS:

Model Year	Models	Model Numbers	Vehicle Identification Number Range
2016	RZR XP Turbo	Z16VDE92AE Z16VDE92AH Z16VDE92AV	Reference "Unit Inquiry" on the dealer website or the Service Bulletin list on the STOP site to lookup affected units.

#### CUSTOMER NOTIFICATION:

Polaris will be mailing a notification letter to consumers with affected registered units in the United States and Canada. The letter will include an explanation of the issue and direct consumers to their dealer to complete the repair. An example of this consumer letter can be found at the end of this bulletin.

In addition to the notification sent by Polaris, dealers should review their sales records and notify customers that have an affected VIN. Dealers are also required to correct any wholegood stock in their inventory as of the date of bulletin release by repairing the vehicle and filing Z-15-04. Reference the STOP site for a list of units with open Service Bulletins at your dealership

#### WARRANTY / PARTS INFORMATION:

A single group claim may be submitted listing the complete (17 digit) Vehicle Identification Number for machines with the same model number. File claim type **SB (Service Bulletin)**. Do **NOT** put more than one model number on a claim.

SERVICE BULLETIN #	Z-15-04
CLAIM TYPE	SB (Service Bulletin)
LABOR ALLOWANCE	0.3 Hrs. (18 minutes)
PART NUMBER / DESCRIPTION	7170107 (QTY 1) BULLETIN COMPLETION DECAL
PARTS AVAILABILITY	None required
DIRECT-SHIP FROM POLARIS	NO